



3/25/15 – Entrance to asbestos containing material zone. Exits through shower.



3/25/15 – Asbestos abatement activities on main floor



3/25/15 – Sealed asbestos debris container. Containers to be shipped to Colorado disposal site.



4/3/15 – Asbestos abatement conditions after operations. Holes in cement block are related to extracting asbestos containing material (vermiculite) insulation from the block voids.



4/3/15 – Asbestos abatement operations. Note ceiling demolition performed.