



1/29/15 – Structural steel erection



1/29/15 – Masonry wall erection



1/29/15 – Masonry wall erection



*2/12/15 – Masonry wall and main floor structural erection*



*2/12/15 – Structural steel erection progress*



*2/12/15 – Electrical panel progress in basement*



*2/26/15 – Structural steel erection progress*



*2/26/15 – Concrete pour preparations for HVAC penthouse*



*3/12/15 – Last remaining barrel roof truss installation*




*3/12/15 – Storm drainage improvements ready for installation*



*3/12/15 – Main floor framing progress*



*4/16/15 – Exterior view from south*



*4/16/15 – Interior view from north end of library, focusing on barrel roofline*



*4/16/15 – Interior view looking north from main library entryway*



*4/16/15 – Basement construction progress*



*5/1/15 – Exterior library progress*



*5/1/15 – Parking Lot reconstruction*



*4/30/15 – Access floor installation*



*4/30/15 – Interior view looking south from north stairwell; Access floor in foreground*



*5/14/15 – Exterior library progress*



*5/14/15 – Parking Lot reconstruction*



*5/14/15 – Interior progress, looking north from library main entrance*



*5/14/15 – Basement finishing*